

## CURING TIME - FHB II P / FHB II-PF

Temperature at anchoring base	Curing time	
	FHB II-P	FHB II-PF
- 5°C - ± 0°C	240 min.	8 min.
± 0°C - +10°C	45 min.	6 min.
+10°C - + 20°C	20 min.	4 min.
≥ + 20°C	10 min.	2 min.

Please note: The curing times apply for dry anchoring bases, in damp anchoring bases they should be doubled.